

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sacramento Maintenance Yard Sacramento Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento Bypass or North Levee	Right	1.74	09/16/2015 09/16/2015	Jai Lor

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_ST0008_01_s _ 2013_3				
Action/Comments					
Inspector Comments: The Sacramento Maintenance Yard has levee manuals.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_ST0008_01_s _ 2013_4				
Action/Comments					
Inspector Comments: The Sacramento Maintenance Yard maintains a stockpile of flood response material.					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_ST0008_01_s _ 2013_5				
Action/Comments					
Inspector Comments: The Sacramento Yard has a written response plan and regular flood response training.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sacramento Maintenance Yard Sacramento Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento Bypass or North Levee	Right	1.74	09/16/2015 09/16/2015	Jai Lor

LM Start	0.01	Rating **	A	Issue No.	6
LM End	1.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.607170 °	38.599512 °
				-121.560117 °	-121.590178 °
DWR ID	DWR_ST0008_01_f_2015_6				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Vegetation on the slope has been maintained.					

Photo 1 of 1 : FA_2015_ST0008_284_6_20150921_00002.jpg



View of the vegetation on the landward side of the levee looking upstream. Photo taken at levee mile 1.73. Fall 2015.

LM Start	0.01	Rating **	A	Issue No.	7
LM End	1.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.607170 °	38.599512 °
				-121.560117 °	-121.590178 °
DWR ID	DWR_ST0008_01_f_2015_7				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Vegetation has been burned and dragged.					

Photo 1 of 1 : FA_2015_ST0008_284_7_20150921_00003.jpg



View of the vegetation on the waterward side of the levee looking upstream. Photo taken at levee mile 1.73. Fall 2015.

LM Start	0.94	Rating **	M	Issue No.	10
LM End	0.94	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.602763 °	38.602763 °
				-121.576288 °	-121.576288 °
DWR ID	DWR_ST0008_01_f_2015_10				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA_2015_ST0008_284_10_20150921_00007.jpg



View of the rodent holes on the landward side of the levee looking upstream. Fall 2015.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sacramento Maintenance Yard Sacramento Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento Bypass or North Levee	Right	1.74	09/16/2015 09/16/2015	Jai Lor

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Sacramento Maintenance Yard Sacramento Bypass

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento Bypass or South Levee	Left	1.79	09/16/2015 09/16/2015	Jai Lor

LM Start	0.01	Rating **	A	Issue No.	3
LM End	1.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.602735 °	38.597894 °
				-121.555753 °	-121.574759 °
DWR ID	DWR_ST0008_02_f_2015_3				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: The vegetation has been mowed and burned and there is no visibility obstruction.					

Photo 1 of 1 : FA_2015_ST0008_285_3_20150921_00004.jpg



Looking at the vegetation on the waterward side of the levee looking downstream. Fall 2015.

LM Start	0.01	Rating **	A	Issue No.	2
LM End	1.78	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.602735 °	38.594626 °
				-121.555753 °	-121.586689 °
DWR ID	DWR_ST0008_02_f_2015_2				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: The slope has been burned and there is no obstruction to visibility.					

Photo 1 of 1 : FA_2015_ST0008_285_2_20150921_00003.jpg



View of the vegetation on the landward side of the levee looking downstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--